

<b>Current Summary of Airworthiness Directives, Technical Notes and Service Bulletins</b>				<b>Type: NL - STU</b>	<b>Registr.-Sign</b>
<b>Ballonbau Wörner GmbH</b> <b>Flughafenstraße 20</b> <b>D-86169 Augsburg</b>		<b>DE.PART. 21G.0007</b> <b>DE.CAO.0088</b>		<b>Specification No:</b> <b>EASA.BA.009</b>	<b>Serial-No.:</b>  <b>Page 1</b>
<b>AD-No.:</b> <b>Date of Issue:</b>	<b>TN/CN/SB-No.:</b> <b>Date of Issue:</b>	<b>Applies for</b> <b>Type Series and Serial-No.:</b>	<b>Item:</b>	<b>Date:</b>	<b>Check Note:</b>
	TN 8038 – 1 24.06.1994	Type Series NL-280 - 840/STU since Serial No.1042	Modification of the number of parachute lines and pull down belts		
	TN 8038 -2 24.06.1994	Type Series NL-280 - 1000/STU	Modification of the position of the holding ropes		
	TN 8038 – 3 24.06.1994	all Type Series since Serial-No.1038	Supplements to the Instruction Manual		
	TN 8038 – 4 23.02.1995	Type Series NL – STU all new baskets since Serial-No.5055	Mounting of a flap in the basket side;basket sizes IV, V and VI	optional	
	TN 8038 – 5 13.11.1997	Type Series NL - STU	Parachute	March 1998	
	TN 8038 - 4.1 05.08.1998	Type Series NL - STU	Add-on to TN 8038-4 for the basket size III		
	TN 8038 – 6 05.08.1998	Type Series NL - STU	Adjustment		
	TN 8038 – 7 15.03.1999	Type Series NL-STU - on demand -	Limitation of the basket sizes V and VI to maximum 4 passengers		
	TN 8038 – 8 28.11.2000	Type Series NL-STU since Serial-No.1067 since Serial-No.1039 in case of replacement of the parachute rope and/or the emergency rope	Parachute rope		
	TN 8038 – 9 06.11.2001	NL – STU all delivered balloons	Modification of the instructions for packing the envelope and placing of an edge protection	within 4 weeks	
	TN 8038 – 10 16.08.2004	NL – STU since Serial-No.1083	Fabric of the envelope with modified coating		

n. a. = not affected

Date of examination:

<b>Current Summary of Airworthiness Directives, Technical Notes and Service Bulletins</b>				<b>Type: NL - STU</b>	<b>Registr.-Sign</b>
<b>Ballonbau Wörner GmbH</b> <b>Flughafenstraße 20</b> <b>D-86169 Augsburg</b>		<b>DE.PART. 21G.0007</b> <b>DE.CAO.0088</b>		<b>Specification No:</b> <b>EASA.BA.009</b>	<b>Serial-No.:</b>  <b>Page 2</b>
<b>AD-No.:</b> <b>Date of Issue:</b>	<b>TN/CN/SB-No.:</b> <b>Date of Issue:</b>	<b>Applies for</b> <b>Type Series and Serial-No.:</b>	<b>Item:</b>	<b>Date:</b>	<b>Check Note:</b>
	TN 8038 – 7.1 16.05.2005	NL – STU on demand	Basket size VI		
	TN 8038 – 11 31.05.2005	NL – STU	Approved repair procedures		
	CN EASA.BA.009-1 22.12.2006	NL – STU Since Serial-No.1087	Butt-seam for envelope joints		
	TN EASA.BA.009-2 11.12.2008	NL – STU Since Serial-No.1039	Bolt ropes of the parachute		
	TN EASA.BA.009-3 04.05.2009	NL – STU optional	Repair procedures for electrically conductive coatings		
	TN EASA.BA.009-4 02.07.2009	NL – STU Since Serial-No.1038	Modification of the maintenance part		
	TN EASA.BA.009-3.1 15.05.2013	NL-STU Serial-No.: 1087, 1088, 1089, 1090, 1091, 1092	Repair procedures for electrically conductive coatings		
AD No.: 2013-0293 of 09 <sup>th</sup> Dec. 2013	TN EASA.BA.009-6 07.11.2013	NL-STU Since Serial-No.1038 included.	1. Separation of the Flight- and Instruction Manual, Issue 1 of, January 1993, in a separate Flight Manual and Instructions for Continued Airworthiness	Dec.23, 2013	
AD No.: 2013-0293 of 09 <sup>th</sup> Dec. 2013	TN EASA.BA.009-6 Nov. 07, 2013	NL-STU Since Serial-No.1038 included.	2. Modification of the Airworthiness Limitation Section in the Instructions for Continued Airworthiness	Dec.23, 2013	

n. a. = not affected

Date of examination:

<b>Current Summary of Airworthiness Directives, Technical Notes and Service Bulletins</b>				<b>Type: NL - STU</b>	<b>Registr.-Sign</b>
<b>Ballonbau Wörner GmbH</b> <b>Flughafenstraße 20</b> <b>D-86169 Augsburg</b>		<b>DE.PART. 21G.0007</b> <b>DE.CAO.0088</b>		<b>Specification No:</b> <b>EASA.BA.009</b>	<b>Serial-No.:</b>  <b>Page 3</b>
<b>AD-No.:</b> <b>Date of Issue:</b>	<b>TN/CN/SB-No.:</b> <b>Date of Issue:</b>	<b>Applies for</b> <b>Type Series and Serial-No.:</b>	<b>Item:</b>	<b>Date:</b>	<b>Check Note:</b>
	TN EASA.BA.009-7 May 05, 2014	NL-STU Since Serial-No.1039 included	Integration of ULTRAMAGIC TEKNO-Baskets Serial-No.: CT-01/33 and CT-02/05		
	CN EASA.BA.009-8 Aug. 08, 2014	all Type-Series	Qualification of glue for all Type-Series		
	SB 009-1 Aug. 06, 2015	all Type-Series	Porosity Test	Aug.10, .2015	
	SB 009-2 June 13, 2016	NL-STU Since serial no. 1039	Issue 2.0 of the English Flight Manual May 2016		
	TN 009-9 July 08, 2016	NL-STU Since serial no. 1039	Issue 2.0 of the German Flight Manual May 2016		
	TN 009-10 September 12, 2016	NL-STU All since 1993	Modification of the light weight basket (fabric walled basket)		
	TN 009-11 May 10, 2019	NL-STU all Type Series	Adaption of the Flight Manual to industrial rules regarding the handling of gases		
	TN EASA.BA.006-23 June 19, 2020	All Type-Series	Water-based paint		
	TN 009-12 Dec. 02, 2020	NL-STU All Type Series	Additional horizontal seams	optional	

.....  
Examiner of Aircraft Cat. L

n. a. = not affected

Date of examination: