



BBW-Formblatt Nr. 35 Übersicht über AD/LTA/SB/Modification/Repair

Type:	NL-STU	Specification No	EASA.BA.009	Registr.-Sign		Serial-No	
Brief description of the AD/LTA/SB/Modification/Repair/Status							Erledigungsvermerk
EASA-AD, LTA-No. Date of issue	SB- M/Modifica- tion/Repair-Nr. Date of issue	Aff. series, serial no, component	Measures	Dates and deadlines		Measure implemented Audit certificate / stamp	
	TN 8038 – 1 24.06.1994	NL-280 - 840/STU since Serial No.: 1042	Modification of the number of parachute lines and pull down belts				
	TN 8038 -2 24.06.1994	Type Series NL-280 - 1000/STU	Modification of the position of the holding ropes				
	TN 8038 – 3 24.06.1994	all Type Series since Serial-No.1038	Supplements to the Instruction Manual				
	TN 8038 – 4 23.02.1995	Type Series NL – STU all new baskets since Serial-No.5055	Mounting of a flap in the basket side;basket sizes IV, V and VI	optional			
	TN 8038 – 5 13.11.1997	Type Series NL - STU	Parachute	March 1998			
	TN 8038 - 4.1 05.08.1998	Type Series NL - STU	Add-on to TN 8038-4 for the basket size III				
	TN 8038 – 6 05.08.1998	Type Series NL - STU	Adjustment				
	TN 8038 – 7 15.03.1999	Type Series NL-STU - on demand -	Limitation of the basket sizes V and VI to maximum 4 passengers				



Type:	NL-STU	Specification No	EASA.BA.009	Registr.-Sign		Serial-No	
Brief description of the AD/LTA/SB/Modification/Repair/Status							Erledigungsvermerk
EASA-AD, LTA-No. Date of issue	SB- M/Modifica- tion/Repair-Nr. Date of issue	Aff. series, serial no, component	Measures		Dates and deadlines		Measure implemented Audit certificate / stamp
	TN 8038 – 8 28.11.2000	Type Series NL-STU since Serial-No.1067 since Serial- No.1039 in case of replacement of the parachute rope and/or the emer- gency rope	Parachute rope				
	TN 8038 – 9 06.11.2001	NL – STU all delivered balloons	Modification of the instructions for packing the en- velope and placing of an edge protection		within 4 weeks		
	TN 8038 – 10 16.08.2004	NL – STU since Serial-No.1083	Fabric of the envelope with modified coating				
	TN 8038 – 7.1 16.05.2005	NL – STU on demand	Basket size VI				
	TN 8038 – 11 31.05.2005	NL – STU	Approved repair procedures				
	CN EASA.BA.009-1 22.12.2006	NL – STU Since Serial- No.1087	Butt-seam for envelope joints				
	TN EASA.BA.009-2 11.12.2008	NL – STU Since Serial- No.1039	Bolt ropes of the parachute				



Type:	NL-STU	Specification No	EASA.BA.009	Registr.-Sign	Serial-No	
Brief description of the AD/LTA/SB/Modification/Repair/Status						Erledigungsvermerk
EASA-AD, LTA-No. Date of issue	SB- M/Modifica- tion/Repair-Nr. Date of issue	Aff. series, serial no, component	Measures	Dates and deadlines	Measure implemented Audit certificate / stamp	
	TN EASA.BA.009-3 04.05.2009	NL – STU optional	Repair procedures for electrically conductive coat- ings			
	TN EASA.BA.009-4 02.07.2009	NL – STU Since Serial- No.1038	Modification of the maintenance part			
	TN EASA.BA.009-3.1 15.05.2013	NL-STU Serial-No.: 1087, 1088, 1089, 1090, 1091, 1092	Repair procedures for electrically conductive coat- ings			
AD No.: 2013-0293 of 09th Dec. 2013	TN EASA.BA.009-6 07.11.2013	NL-STU Since Serial- No.1038 included.	1. Separation of the Flight- and Instruction Manual, Issue 1 of, January 1993, in a separate Flight Manual and In- structions for Continued Airworthiness	Dec.23, 2013		
AD No.: 2013-0293 of 09th Dec. 2013	TN EASA.BA.009-6 Nov. 07, 2013	NL-STU Since Serial- No.1038 included.	2. Modification of the Airworthiness Limitation Sec- tion in the Instructions for Continued Airworthiness	Dec.23, 2013		
	TN EASA.BA.009-7 May 05, 2014	NL-STU Since Serial- No.1039 included	Integration of ULTRAMAGIC TEKNO-Baskets Se- rial-No.: CT-01/33 and CT-02/05			



Type:	NL-STU	Specification No	EASA.BA.009	Registr.-Sign	Serial-No	
Brief description of the AD/LTA/SB/Modification/Repair/Status						Erledigungsvermerk
EASA-AD, LTA-No. Date of issue	SB- M/Modifica- tion/Repair-Nr. Date of issue	Aff. series, serial no, component	Measures	Dates and deadlines	Measure implemented Audit certificate / stamp	
	CN EASA.BA.009-8 Aug. 08, 2014	all Type-Series	Qualification of glue for all Type-Series			
	SB 009-1 June 13, 2016	all Type-Series	Porosity Test	Aug.10, .2015		
	SB 009-2 June 13, 2016	NL-STU Since serial no. 1039	Issue 2.0 of the English Flight Manual May 2016			
	TN 009-9 July 08, 2016	NL-STU Since serial no. 1039	Issue 2.0 of the German Flight Manual May 2016			
	TN 009-10 September 12, 2016	NL-STU All since 1993	Modification of the light weight basket (fabric walled basket)			
	TN 009-11 May 10, 2019	NL-STU All Type-Series	Adaption of the Flight Manual to industrial rules re- garding the handling of gases			
	TN EASA.BA.006-23 June 19, 2020	All Type-Series	Water-based paint			
	TN 009-12 Dec. 02, 2020	NL-STU All Type-Series	Additional horizontal seams	optional		
	TN EASA.BA.006-27 10081795 27.04.2023	NL-STU All Type-Series	Change of material specifications BBW-PA50,PU, BBW-PA-110,PU and BBW-PES280,PU to intro- duce optional printing on envelope material for de- sign purposes. Change of address			



Ballonbau Wörner GmbH
Flughafenstraße 20
86169 Augsburg

CAE (CAO-Handbuch)
BBW-Formblatt Nr. 35

Ausgabe 2, Revision 2
DE.CAO.0088

Type:	NL-STU	Specification No	EASA.BA.009	Registr.-Sign		Serial-No	
Brief description of the AD/LTA/SB/Modification/Repair/Status							Erledigungsvermerk
EASA-AD, LTA-No. Date of issue	SB- M/Modifica- tion/Repair-Nr. Date of issue	Aff. series, serial no, component	Measures	Dates and deadlines		Measure implemented Audit certificate / stamp	
	TN EASA.BA.009-13 10086350 05.02.2025	NL-STU All Type-Series	Repair Instruction Electro Static Discharge				
	TM EASA.BA.009-14 10090521 27.07.2026	NL-STU All from 1993 on	Introduction of a Race Competition Basket				
	TM EASA.BA.009-14 10090521 27.07.2026	NL-STU All Type-Series	Amendment to the Flight Manual, Amendment to the Maintenance Manual				

Date:		Audit certificate / stamp Examiner of Aircraft L3H/L3G	
-------	--	---	--